

Gladstone Wharf Remediation Works

SRG Global

Project Overview:

DESCRIPTION:

As part of ongoing wharf remediation works, safe access was required to maintain and repair concrete piles located beneath the wharf structure. A durable and safe working platform was essential to support crews operating in challenging marine conditions.

PROBLEM:

Maintenance under the wharf required direct access to the piles, but the confined and exposed environment posed significant safety risks. Traditional scaffold platforms were not sufficient without a reliable decking material to ensure stability, slip resistance, and long-term performance in a corrosive marine setting.

NEED:

- Safe, non-slip decking system suitable for scaffold working platforms
- Non-corrosive materials able to withstand harsh marine exposure
- Lightweight, easy-to-install solution to save time on site and improve worker efficiency

SOLUTION:

Terra Firma FRP Moulded Grating (RAL 7015)

